











10/01/2016 to 11/27/2017

Rpt No:AV-201

Class A Mishaps

Page 6 of 9

**Mishap Date** 07/10/2017      **Time** 1621    **Severity** A GM    **Event Cost** \$4,052,964  
**Reference** VMM-261                      **DTG** 000000XXX00                      **HT ID** 1499815425735

<b>Acft</b> MV022B	<b>Count</b> Y	<b>Destroyed</b> U	<b>Major Command</b> MARFORCOM
<b>Custodian</b> VMM-261			<b>Buno</b> 168349
<b>Fatalities</b> 1			

**Location** NEW RIVER MCAS SHORE MCAS NEW RIVER

**Summary** MV-22B: Maintainers struck by lightning on the flight line.

**Mishap Date** 07/15/2017      **Time** 1500    **Severity** A FM    **Event Cost** \$0  
**Reference** VFA-154                      **DTG** 000000XXX00                      **HT ID** 1500190034570

<b>Acft</b> F018F	<b>Count</b> Y	<b>Destroyed</b> N	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> VFA-154			<b>Buno</b> 166883
<b>Fatalities</b> 0			

**Location** .

**Summary** Engine borescope plug backed out in flight causing hot air to burn engine bay and aircraft skin

**Mishap Date** 08/04/2017      **Time** 1604    **Severity** A FM    **Event Cost** \$83,195,000  
**Reference** VMM-265                      **DTG** 000000XXX00                      **HT ID** 1501925672884

<b>Acft</b> MV022B	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> MARFORPAC
<b>Custodian</b> VMM-265			<b>Buno</b> 168634
<b>Fatalities</b> 3			

**Location** Eastern Coast of Australia

**Summary** On approach to LPD, aircraft struck ship and then impacted water on starboard quarter of the ship.

**Mishap Date** 08/04/2017      **Time** 1830    **Severity** A FM    **Event Cost** \$5,000,000  
**Reference** VFA-22                          **DTG** 000000XXX00                      **HT ID** 1501986383271

<b>Acft</b> F018F	<b>Count</b> Y	<b>Destroyed</b> N	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> VFA-22			<b>Buno</b> 166976
<b>Fatalities</b> 0			

**Location** PACIFIC OCEAN (GENERAL) SHIP

**Summary** F-18F impacted round down with right horizontal stabilator upon landing. Diverted successfully.

10/01/2016 to 11/27/2017

Rpt No:AV-201

Class A Mishaps

Page 7 of 9

---

<b>Mishap Date</b>	08/08/2017	<b>Time</b>	1238	<b>Severity</b>	A FM	<b>Event Cost</b>	\$2,700,000
<b>Reference</b>	VFC-111	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1502308995787

<b>Acft</b>	F005N	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	NAVAL RESERVE
<b>Custodian</b>	VFC-111					<b>Buno</b>	761533
<b>Fatalities</b>	0						

**Location**

**Summary** F-5N aircraft crashed during a training mission.

---

<b>Mishap Date</b>	08/11/2017	<b>Time</b>	1245	<b>Severity</b>	A FM	<b>Event Cost</b>	\$0
<b>Reference</b>	VFA-146	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1502542138704

<b>Acft</b>	F018E	<b>Count</b>	Y	<b>Destroyed</b>	U	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	VFA-146					<b>Buno</b>	165865
<b>Fatalities</b>	0						

**Location** ARABIAN GULF (SOUTHERN)

**Summary** Aircrew ejected after landing following aircraft divert from USS ship due to engine anomalies.

---

<b>Mishap Date</b>	08/16/2017	<b>Time</b>	2247	<b>Severity</b>	A FRM	<b>Event Cost</b>	\$0
<b>Reference</b>	HSM-73	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1503129608290

<b>Acft</b>	MH060R	<b>Count</b>	Y	<b>Destroyed</b>	N	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	HSM-73					<b>Buno</b>	168124
<b>Fatalities</b>	0						

**Location**

**Summary** Aircraft SONAR Transducer lost at sea.

---

10/01/2016 to 11/27/2017

Rpt No:AV-201

Class A Mishaps

Page 8 of 9

---

<b>Mishap Date</b>	09/13/2017	<b>Time</b>	1735	<b>Severity</b>	A FM	<b>Event Cost</b>	\$0
<b>Reference</b>	VAQRON-136	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1505444524526

<b>Acft</b>	EA018G	<b>Count</b>	Y	<b>Destroyed</b>	N	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	VAQRON-136					<b>Buno</b>	168273
<b>Fatalities</b>	0						
<b>Acft</b>	F018E	<b>Count</b>	N	<b>Destroyed</b>	N	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	VFA-137					<b>Buno</b>	165902
<b>Fatalities</b>	0						

**Location**

**Summary** MIDAIR between an EA-18G and FA-18E in the FRTC. Both aircraft recovered safely at NAS Fallon.

---

<b>Mishap Date</b>	09/18/2017	<b>Time</b>	2330	<b>Severity</b>	A GM	<b>Event Cost</b>	\$0
<b>Reference</b>	VX-31	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1505941184323

<b>Acft</b>	F018F	<b>Count</b>	Y	<b>Destroyed</b>	N	<b>Major Command</b>	NAVAIRSYSCOM
<b>Custodian</b>	NAVTESTWINGPAC					<b>Buno</b>	166968
<b>Fatalities</b>	0						

**Location**

**Summary** Engine fire occurred while motoring R ENG during water wash.

---

<b>Mishap Date</b>	09/27/2017	<b>Time</b>	0410	<b>Severity</b>	A FM	<b>Event Cost</b>	\$81,700,000
<b>Reference</b>	VMM-364	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1506657156433

<b>Acft</b>	MV022B	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORPAC
<b>Custodian</b>	VMM-364					<b>Buno</b>	168281
<b>Fatalities</b>	0						

**Location**

**Summary** Aircraft sustained damage while conducting general support.

---

10/01/2016 to 11/27/2017

Rpt No:AV-201

Class A Mishaps

Page 9 of 9

**Mishap Date** 09/30/2017      **Time** 1700    **Severity** A FM    **Event Cost** \$41,000,000  
**Reference** VT-7                      **DTG** 000000XXX00                      **HT ID** 1506898513678

**Acft** T045C                      **Count** Y    **Destroyed** Y                      **Major Command** CNATRA  
**Custodian** VT-7    **Buno** 165632  
**Fatalities** 0

**Location** 30NM SW of Knoxville.

**Summary** Single T-45C crash on day low level.

**Mishap Date** 10/10/2017      **Time** 1714    **Severity** A FM    **Event Cost** \$0  
**Reference** HMM 462 FPO SF                      **DTG** 000000XXX00                      **HT ID** 1507720215718

**Acft** CH053E                      **Count** Y    **Destroyed** U                      **Major Command** MARFORPAC  
**Custodian** HMM 462 FPO SF    **Buno** 163078  
**Fatalities** 0

**Location**

**Summary** CH-53E engine fire in flight, emergency landing. No injuries to aircrew.

**Mishap Date** 11/06/2017      **Time** 1315    **Severity** A FM    **Event Cost** \$0  
**Reference** VP-26                      **DTG** 000000XXX00                      **HT ID** 1509997999184

**Acft** P008A                      **Count** Y    **Destroyed** N                      **Major Command** COMNAVAIRLANT  
**Custodian** VP-26    **Buno** 168431  
**Fatalities** 0

**Location**

**Summary** P-8A executed full stop landing after experiencing engine overheat conditions and visible flames.

**Mishap Date** 11/22/2017      **Time** 1530    **Severity** A FM    **Event Cost** \$64,550,000  
**Reference** VRC-30 DET 5                      **DTG** 000000XXX00                      **HT ID** 1511338245480

**Acft** C002A                      **Count** Y    **Destroyed** Y                      **Major Command** COMNAVAIRPAC  
**Custodian** VRC-30 DET 5    **Buno** 162175  
**Fatalities** 3

**Location**

**Summary** C-2A ditched while inbound to CVN with 11 onboard. Three fatalities.