

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 1 of 9

Mishap Date 10/13/2016 **Time** 0030 **Severity** A FM **Event Cost** \$0
Reference VQ-3 SEA COMP **DTG** 000000XXX00 **HT ID** 1476394075639

Acft E006B **Count** Y **Destroyed** N **Major Command** COMNAVAIRPAC
Custodian VQ-3 SEA COMP **Buno** 164408
Fatalities 0

Location TINKER AFB

Summary Bird ingested in #2 engine with damage to compressor blades noted upon conditional inspection.

Mishap Date 10/20/2016 **Time** 1912 **Severity** A FM **Event Cost** \$57,512,520
Reference HMM-465 **DTG** 000000XXX00 **HT ID** 1477345861529

Acft CH053E **Count** Y **Destroyed** Y **Major Command** MARFORPAC
Custodian HMM-465 **Buno** 164781
Fatalities 0

Location YUMA SHORE Combat Town R2301W Yuma Range Complex

Summary CH-53E impacted a shipping container while conducting RVL at MAWTS-1 during WTI 1-17

Mishap Date 10/25/2016 **Time** 1815 **Severity** A FM **Event Cost** \$74,000,000
Reference VMFA-251 **DTG** 000000XXX00 **HT ID** 1477448751427

Acft F018C **Count** Y **Destroyed** Y **Major Command** MARFORCOM
Custodian VMFA-251 **Buno** 164238
Fatalities 0

Location TWENTYNINE PALMS EAF SHORE

Summary Pilot ejected safely from aircraft during landing at the 29 Palms Expeditionary Landing Field.

Mishap Date 10/27/2016 **Time** 0937 **Severity** A FM **Event Cost** \$2,000,001
Reference VMFAT-501 WARLORDS **DTG** 000000XXX00 **HT ID** 1477594349811

Acft F035B **Count** Y **Destroyed** U **Major Command** MARFORCOM
Custodian VMFAT-501 WARLORDS **Buno** 168057
Fatalities 0

Location BEAUFORT MCAS SHORE Landing Pattern

Summary FIRE WPN BAY R, IPP FAIL, HYD FAIL B in the landing pattern.

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 2 of 9

Mishap Date 11/09/2016 **Time** 1142 **Severity** A FM **Event Cost** \$84,200,000
Reference VMFA-314 **DTG** 000000XXX00 **HT ID** 1478736762470

Acft	F018A+	Count	Y	Destroyed	Y	Major Command	MARFORPAC
Custodian	VMFA-314					Buno	163102
Fatalities	0						
Acft	F018A+	Count	N	Destroyed	N	Major Command	MARFORPAC
Custodian	VMFA-314					Buno	163137
Fatalities	0						

Location PACIFIC OCEAN (EASTERN - EASTPAC) SAN DIEGO SHORE

Summary F/A-18A: Two F/A-18s have a midair during a HABFM sortie

Mishap Date 11/21/2016 **Time** 1548 **Severity** A FM **Event Cost** \$3,300,000
Reference VFA-122 **DTG** 000000XXX00 **HT ID** 1479838421972

Acft	F018F	Count	Y	Destroyed	N	Major Command	COMNAVAIRPAC
Custodian	VFA-122					Buno	166847
Fatalities	0						

Location LEMOORE NAS SHORE Sidewinder Low Level Between Points B and C

Summary F/A-18F: Aircraft impacted a tree during low level training. Aircraft recovered safely.

Mishap Date 12/07/2016 **Time** 1836 **Severity** A FM **Event Cost** \$76,500,000
Reference VMFA-115 **DTG** 000000XXX00 **HT ID** 1481118093282

Acft	F018C	Count	Y	Destroyed	Y	Major Command	MARFORCOM
Custodian	VMFA-115					Buno	163755
Fatalities	1						

Location PACIFIC OCEAN (WESTERN - WESTPAC) IWAKUNI MCAS WATER

Summary F/A-18C+ Ejection at Night Over Water

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 3 of 9

Mishap Date 12/12/2016 **Time** 2118 **Severity** A FM **Event Cost** \$81,789,705
Reference VMM-265 **DTG** 000000XXX00 **HT ID** 1483660001837

Acft MV022B **Count** Y **Destroyed** Y **Major Command** MARFORPAC
Custodian VMM-265 **Buno** 168027
Fatalities 0

Location PHILIPPINE SEA OKINAWA WATER

Summary MV-22 ditched during night AAR training flight.

Mishap Date 12/15/2016 **Time** 1056 **Severity** A GM **Event Cost** \$94,324,924
Reference VAQ-132 **DTG** 000000XXX00 **HT ID** 1481939687033

Acft EA018G **Count** Y **Destroyed** U **Major Command** COMNAVAIRPAC
Custodian VAQ-132 **Buno** 166937
Fatalities 0

Location WHIDBEY ISLAND NAS SHORE NASWI: Hangar 8 Flightline

Summary EA-18G: COCKPIT OVER-PRESSURIZED ON DECK CAUSING CATASTROPHIC CANOPY RUPTURE AND SEVERE INJURIES.

Mishap Date 12/18/2016 **Time** 0600 **Severity** A GM **Event Cost** \$3,000,000
Reference VP-10 **DTG** 000000XXX00 **HT ID** 1482101347834

Acft P008A **Count** Y **Destroyed** N **Major Command** COMNAVAIRLANT
Custodian VP-10 **Buno** 168763
Fatalities 0

Location KADENA AB SHORE Kadena AB

Summary P-8A: Tow bar separation leads to aircraft/tow collision with damage to nose gear and lower fuselage

Mishap Date 01/17/2017 **Time** 1405 **Severity** A FM **Event Cost** \$38,800,000
Reference VT-9 **DTG** 000000XXX00 **HT ID** 1484687820471

Acft T045C **Count** Y **Destroyed** Y **Major Command** CNATRA
Custodian VT-9 **Buno** 165466
Fatalities 0

Location MERIDIAN NAS SHORE Just prior to runway 28 at KNMM.

Summary T-45C: Bird strike during takeoff. MA impacted ground just short of runway during RTB.

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 4 of 9

Mishap Date 01/19/2017 **Time** 0900 **Severity** A GM **Event Cost** \$5,527,200
Reference VAW-124 **DTG** 000000XXX00 **HT ID** 1484856801796

Acft E002C **Count** Y **Destroyed** N **Major Command** COMNAVAIRLANT
Custodian VAW-124 **Buno** 165295
Fatalities 0

Acft E002C **Count** N **Destroyed** U **Major Command** COMNAVAIRLANT
Custodian VAW-124 **Buno** 164483
Fatalities 0

Acft E002C **Count** N **Destroyed** U **Major Command** COMNAVAIRLANT
Custodian VAW-124 **Buno** 165298
Fatalities 0

Location NORFOLK NS SHORE

Summary E-2C: Improper Engine Oil Utilization

Mishap Date 03/28/2017 **Time** 1750 **Severity** A FM **Event Cost** \$0
Reference HSC-85 **DTG** 000000XXX00 **HT ID** 1490674984319

Acft HH060H **Count** Y **Destroyed** N **Major Command** NAVAL RESERVE
Custodian HSC-85 **Buno** 164846
Fatalities 0

Location

Summary ON LANDING MAIN ROTOR BLADES CONTACTED TAIL ROTOR DRIVE SHAFT.

Mishap Date 04/05/2017 **Time** 1310 **Severity** A FM **Event Cost** \$0
Reference HMH-361 **DTG** 000000XXX00 **HT ID** 1491429191763

Acft CH053E **Count** Y **Destroyed** U **Major Command** MARFORPAC
Custodian MARINE HEAVY HELICOPTER SQUADRON 361 HMH-361 **Buno** 164358
Fatalities 0

Location ARIZONA SHORE R2301W IVO MCAS YUMA. MISHAP GRID 11S QR 593 954.

Summary CH-53E CFIT into the desert while conducting RW Defensive Measures.

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 5 of 9

Mishap Date 04/21/2017 **Time** 1837 **Severity** A FM **Event Cost** \$88,700,000
Reference VFA-137 **DTG** 000000XXX00 **HT ID** 1492776201526

Acft F018E **Count** Y **Destroyed** Y **Major Command** COMNAVAIRPAC
Custodian VFA-137 **Buno** 165904
Fatalities 0

Location CELEBES SEA OTHER SHIP

Summary F/A-18E: Aircraft crashed while on final approach to CVN. Pilot ejected safely.

Mishap Date 04/27/2017 **Time** 0657 **Severity** A FM **Event Cost** \$37,700,000
Reference HSM 78 **DTG** 000000XXX00 **HT ID** 1493289747542

Acft MH060R **Count** Y **Destroyed** Y **Major Command** COMNAVAIRPAC
Custodian HSM 78 **Buno** 166549
Fatalities 0

Location PACIFIC OCEAN (WESTERN - WESTPAC) WATER Open Ocean approximately 250 nautical miles East of Guam.

Summary MH-60R: Upon takeoff, aircraft experienced an uncommanded right yaw followed by cut gun into water

Mishap Date 06/25/2017 **Time** 2217 **Severity** A GM **Event Cost** \$2,000,000
Reference VMFA-112 **DTG** 000000XXX00 **HT ID** 1498470628610

Acft F018A+ **Count** Y **Destroyed** U **Major Command** 4TH MAW
Custodian VMFA-112 **Buno** 162428
Fatalities 0

Location MIRAMAR MCAS SHORE On ramp by Hangar 1

Summary FA-18A: Two Marines injured after drip pan fuel caught fire under aircraft. Damage to aircraft also.

Mishap Date 07/10/2017 **Time** 1715 **Severity** A FM **Event Cost** \$70,675,000
Reference VMGR 452 **DTG** 000000XXX00 **HT ID** 1499743483243

Acft KC130T **Count** Y **Destroyed** Y **Major Command** 4TH MAW
Custodian VMGR 452 **Buno** 16500
Fatalities 16

Location

Summary KC-130T BUNO 16500 total loss with 16 personnel on board

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 6 of 9

Mishap Date 07/11/2017 **Time** 1622 **Severity** A GM **Event Cost** \$0
Reference VMM-261 **DTG** 000000XXX00 **HT ID** 1499815425735

Acft	MV022B	Count	Y	Destroyed	U	Major Command	MARFORCOM
Custodian	VMM 261					Buno	168349
Fatalities	0						

Location NEW RIVER MCAS MCAS NEW RIVER

Summary MAINTAINERS STRUCK BY LIGHTNING ON THE FLIGHT LINE WHILE WORKING ON AIRCRAFT.

Mishap Date 07/16/2017 **Time** 1500 **Severity** A FM **Event Cost** \$0
Reference VFA-154 **DTG** 000000XXX00 **HT ID** 1500190034570

Acft	F018F	Count	Y	Destroyed	N	Major Command	COMNAVAIRPAC
Custodian	VFA-154					Buno	166883
Fatalities	0						

Location .

Summary Engine borescope plug backed out in flight causing hot air to burn engine bay and aircraft skin

Mishap Date 08/05/2017 **Time** 1604 **Severity** A FM **Event Cost** \$83,195,000
Reference VMM-265 **DTG** 000000XXX00 **HT ID** 1501925672884

Acft	MV022B	Count	Y	Destroyed	Y	Major Command	MARFORPAC
Custodian	VMM-265					Buno	168634
Fatalities	3						

Location Eastern Coast of Australia

Summary On approach to LPD, aircraft struck ship and then impacted water on starboard quarter of the ship.

Mishap Date 08/05/2017 **Time** 1900 **Severity** A FM **Event Cost** \$0
Reference VFA-22 **DTG** 000000XXX00 **HT ID** 1501986383271

Acft	F018F	Count	Y	Destroyed	N	Major Command	COMNAVAIRPAC
Custodian	VFA-22					Buno	166976
Fatalities	0						

Location

Summary F-18F impacted round down with right horizontal stabilator upon landing. Diverted successfully.

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 7 of 9

Mishap Date	08/09/2017	Time	1238	Severity	A FM	Event Cost	\$2,700,000
Reference	VFC-111	DTG	000000XXX00	HT ID			1502308995787

Acft	F005N	Count	Y	Destroyed	Y	Major Command	NAVAL RESERVE
Custodian	VFC-111					Buno	761533
Fatalities	0						

Location

Summary F-5N aircraft crashed during a training mission.

Mishap Date	08/12/2017	Time	1245	Severity	A FM	Event Cost	\$0
Reference	VFA-146	DTG	000000XXX00	HT ID			1502542138704

Acft	F018E	Count	Y	Destroyed	U	Major Command	COMNAVAIRPAC
Custodian	VFA-146					Buno	165865
Fatalities	0						

Location ARABIAN GULF (SOUTHERN)

Summary Aircrew ejected after landing following aircraft divert from USS ship due to engine anomalies.

Mishap Date	08/17/2017	Time	2247	Severity	A FRM	Event Cost	\$0
Reference	HSM-73	DTG	000000XXX00	HT ID			1503129608290

Acft	MH060R	Count	Y	Destroyed	N	Major Command	COMNAVAIRPAC
Custodian	HSM-73					Buno	168124
Fatalities	0						

Location

Summary Aircraft SONAR Transducer lost at sea.

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 8 of 9

Mishap Date	09/14/2017	Time	1735	Severity	A FM	Event Cost	\$0
Reference	VAQRON-136	DTG	000000XXX00	HT ID			1505444524526

Acft	EA018G	Count	Y	Destroyed	N	Major Command	COMNAVAIRPAC
Custodian	VAQRON-136					Buno	168273
Fatalities	0						
Acft	F018E	Count	N	Destroyed	N	Major Command	COMNAVAIRPAC
Custodian	VFA-137					Buno	165902
Fatalities	0						

Location

Summary MIDAIR between an EA-18G and FA-18E in the FRTC. Both aircraft recovered safely at NAS Fallon.

Mishap Date	09/19/2017	Time	2330	Severity	A GM	Event Cost	\$0
Reference	VX-31	DTG	000000XXX00	HT ID			1505941184323

Acft	F018F	Count	Y	Destroyed	N	Major Command	NAVAIRSYSCOM
Custodian	NAVTESTWINGPAC					Buno	166968
Fatalities	0						

Location

Summary Engine fire occurred while motoring R ENG during water wash.

Mishap Date	09/28/2017	Time	0410	Severity	A FM	Event Cost	\$81,700,000
Reference	VMM-364	DTG	000000XXX00	HT ID			1506657156433

Acft	MV022B	Count	Y	Destroyed	Y	Major Command	MARFORPAC
Custodian	VMM-364					Buno	168281
Fatalities	0						

Location

Summary Aircraft sustained damage while conducting general support.

10/01/2016 to 10/11/2017

Rpt No:AV-201

Class A Mishaps

Page 9 of 9

Mishap Date	10/01/2017	Time	1700	Severity	A FM	Event Cost	\$41,000,000
Reference	VT-7	DTG	000000XXX00	HT ID			1506898513678

Acft	T045C	Count	Y	Destroyed	Y	Major Command	CNATRA
Custodian	VT-7					Buno	165632
Fatalities	0						

Location 30NM SW of Knoxville.

Summary Single T-45C crash on day low level.

Mishap Date	10/11/2017	Time	1714	Severity	A FM	Event Cost	\$0
Reference	HMH 462 FPO SF	DTG	000000XXX00	HT ID			1507720215718

Acft	CH053E	Count	Y	Destroyed	U	Major Command	MARFORPAC
Custodian	HMH 462 FPO SF					Buno	163078
Fatalities	0						

Location

Summary CH-53E engine fire in flight, emergency landing. No injuries to aircrew.