

10/01/2015 to 08/22/2017

Rpt No: AV-201

Class A Mishaps

Page 1 of 12

**Mishap Date** 10/18/2015 **Time** 1326 **Severity** A GM **Event Cost** \$2,000,000  
**Reference** VAW-115 **DTG** 000000XXX00 **HT ID** 1445144936128

**Acft** E002C **Count** Y **Destroyed** N **Major Command** COMNAVAIRPAC  
**Custodian** VAW-115 **Buno** 166505  
**Fatalities** 0

**Location** PACIFIC OCEAN (WESTERN - WESTPAC) SHIP Hangar bay of USS Ship

**Summary** E-2C: Electrical arcing at vapor cycle power receptacle led to aircraft fire in the hangar bay.

**Mishap Date** 10/21/2015 **Time** 1023 **Severity** A FM **Event Cost** \$78,500,000  
**Reference** VMFA 232 **DTG** 000000XXX00 **HT ID** 1446193740657

**Acft** F018C **Count** Y **Destroyed** Y **Major Command** MARFORPAC  
**Custodian** VMFA-232 **Buno** 165181  
**Fatalities** 1

**Location** LAKENHEATH SHORE The impact was in the middle of a farmer's field.

**Summary** A single F/A-18C crashed 6.6 miles northwest of Lakenheath, England.

**Mishap Date** 12/08/2015 **Time** 1700 **Severity** A FM **Event Cost** \$2,000,001  
**Reference** VMM-166 **DTG** 000000XXX00 **HT ID** 1449722105880

**Acft** MV022B **Count** Y **Destroyed** U **Major Command** MARFORPAC  
**Custodian** VMM-166 **Buno** 168026  
**Fatalities** 0

**Location** PACIFIC OCEAN (EASTERN - EASTPAC) SHIP w-291, IVO San Clemente

**Summary** MV-22: While recovering to LPD, MV-22 landed short of spot 2, main landing gear in deck edge netting

**Mishap Date** 01/12/2016 **Time** 0813 **Severity** A FM **Event Cost** \$73,900,000  
**Reference** NAWDC **DTG** 000000XXX00 **HT ID** 1452619409898

**Acft** F018A **Count** Y **Destroyed** Y **Major Command** COMNAVAIRPAC  
**Custodian** NAWDC **Buno** 162837  
**Fatalities** 0

**Location** DIXIE VALLEY SHORE Approximately 26 miles from NAS Fallon (KNFL), north of B-17 restricted area, Fallon Range Training Complex (FRTC), Fallon, NV (east of Stillwater mountain range, north of Hwy 50).

**Summary** FA-18A, Engine Fire Results in Ejection. Pilot Ejected O.K.

10/01/2015 to 08/22/2017

Rpt No: AV-201

Class A Mishaps

Page 2 of 12

**Mishap Date** 01/14/2016      **Time** 2234    **Severity** A FM    **Event Cost** \$119,960,000  
**Reference** HMH 463                      **DTG** 000000XXX00                      **HT ID** 1452879722857

<b>Acft</b>	CH053E	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORPAC
<b>Custodian</b>	HMH 463					<b>Buno</b>	163061
<b>Fatalities</b>	6						
<b>Acft</b>	CH053E	<b>Count</b>	N	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORPAC
<b>Custodian</b>	HMH 463					<b>Buno</b>	161255
<b>Fatalities</b>	6						

**Location** PACIFIC OCEAN (MID - MIDPACIFIC) WAIMEA KOHALA WATER Waialua (approximately 2NM offshore) North of training area.

**Summary** Two CH-53 helicopters crashed while on training flight. All 12 crewmembers deceased.

**Mishap Date** 03/08/2016      **Time** 1306    **Severity** A FM    **Event Cost** \$64,400,000  
**Reference** 26TH MARINE                      **DTG** 000000XXX00                      **HT ID** 1457446421911

<b>Acft</b>	AV008B	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORCOM
<b>Custodian</b>	VMM-162					<b>Buno</b>	165003
<b>Fatalities</b>	0						
<b>Acft</b>	AV008B	<b>Count</b>	N	<b>Destroyed</b>	N	<b>Major Command</b>	MARFORCOM
<b>Custodian</b>	VMM-162					<b>Buno</b>	164121
<b>Fatalities</b>	0						
<b>Acft</b>	AV008B	<b>Count</b>	N	<b>Destroyed</b>	N	<b>Major Command</b>	MARFORCOM
<b>Custodian</b>	VMM-162					<b>Buno</b>	164551
<b>Fatalities</b>	0						

**Location** ARABIAN GULF (NORTHERN) SHIP

**Summary** AV-8B catastrophic engine failure on takeoff. Pilot aborted and egressed successfully.

**Mishap Date** 05/06/2016      **Time** 1645    **Severity** A FM    **Event Cost** \$64,400,000  
**Reference** VMA-542                      **DTG** 000000XXX00                      **HT ID** 1462572979469

<b>Acft</b>	AV008B	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORCOM
<b>Custodian</b>	VMA-542					<b>Buno</b>	165594
<b>Fatalities</b>	0						

**Location** ATLANTIC OCEAN (WESTERN - WESTLANT) WILMINGTON INTL WATER Over the water, 140/12 from the Wilmington TACAN (ILM). Water depth approximately 40'.

**Summary** AV-8B experienced loss of thrust, pilot ejected safely

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 3 of 12

---

**Mishap Date** 05/26/2016      **Time** 1030      **Severity** A FM      **Event Cost** \$173,580,662  
**Reference** VFA-211      **DTG** 000000XXX00      **HT ID** 1464285130476

**Acft** F018F      **Count** Y      **Destroyed** Y      **Major Command** COMNAVAIRLANT  
**Custodian** VFA-211      **Buno** 166813  
**Fatalities** 0

**Location** ATLANTIC OCEAN (MID - MIDLANT) ELIZABETH CITY WATER

**Summary** 2xF/A-18F Collided during Air-to-Air training. 2 aircraft lost. No fatalities.

---

**Mishap Date** 05/29/2016      **Time** 2109      **Severity** A FM      **Event Cost** \$3,792,077  
**Reference** VAQ-133      **DTG** 000000XXX00      **HT ID** 1464539948671

**Acft** EA018G      **Count** Y      **Destroyed** N      **Major Command** COMNAVAIRPAC  
**Custodian** VAQ-133      **Buno** 168379  
**Fatalities** 0

**Location** SOUTH CHINA SEA SHIP South China Sea

**Summary** EA-18G inflight engagement during night CV landing caused extensive damage to aircraft

---

**Mishap Date** 06/02/2016      **Time** 1501      **Severity** A FM      **Event Cost** \$78,500,000  
**Reference** NAVFLIGHTDEMRON      **DTG** 000000XXX00      **HT ID** 1464903810034

**Acft** F018C      **Count** Y      **Destroyed** Y      **Major Command** CNATRA  
**Custodian** NAVFLIGHTDEMRON      **Buno** 163455  
**Fatalities** 1

**Location** SMYRNA SHORE Near Smyrna, TN

**Summary** F/A-18 impacted ground during air show practice

---

**Mishap Date** 06/14/2016      **Time** 1110      **Severity** A FM      **Event Cost** \$25,508,816  
**Reference** HSC-2      **DTG** 000000XXX00      **HT ID** 1465921426974

**Acft** MH060S      **Count** Y      **Destroyed** Y      **Major Command** COMNAVAIRLANT  
**Custodian** HSC-2      **Buno** 165750  
**Fatalities** 0

**Location** CHESAPEAKE BAY WATER James River IVO Newport News

**Summary** MH-60S crashed into James River while performing SAR training flight.

---

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 4 of 12

**Mishap Date** 07/15/2016      **Time** 1505    **Severity** A GM    **Event Cost** \$2,681,687  
**Reference** VAQ-131                      **DTG** 000000XXX00                      **HT ID** 1472751380121

<b>Acft</b> EA018G	<b>Count</b> Y	<b>Destroyed</b> N	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> VAQ-131			<b>Buno</b> 168776
<b>Fatalities</b> 0			

**Location** WHIDBEY ISLAND NAS SHORE Flight Line

**Summary** EA-18G: PKP ingestion caused significant ECS and engine damage

**Mishap Date** 07/28/2016      **Time** 2150    **Severity** A GM    **Event Cost** \$2,000,000  
**Reference** VMGR-452                      **DTG** 000000XXX00                      **HT ID** 1469814130901

<b>Acft</b> KC130T	<b>Count</b> Y	<b>Destroyed</b> U	<b>Major Command</b> 4TH MAW
<b>Custodian</b> VMGR-452			<b>Buno</b> 163592
<b>Fatalities</b> 0			

**Location** CITY OF COLORADO SPRINGS MUNI SHORE PETERSON FLD, CO (KCOS).

**Summary** KC130T EXPERIENCED HAIL DAMAGE WHILE PARKED ON THE RAMP AT PETERSON FLD, CO (KCOS).

**Mishap Date** 07/28/2016      **Time** 2230    **Severity** A FM    **Event Cost** \$78,500,000  
**Reference** VMFA 232                      **DTG** 000000XXX00                      **HT ID** 1469785772068

<b>Acft</b> F018C	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> MARFORPAC
<b>Custodian</b> VMFA 232			<b>Buno</b> 165194
<b>Fatalities</b> 1			

**Location** TWENTYNINE PALMS SHORE MCAGCC Twentynine Palms

**Summary** F/A-18C crash during night air-to-ground training mission

**Mishap Date** 08/02/2016      **Time** 1040    **Severity** A FM    **Event Cost** \$77,400,000  
**Reference** VMFA 232                      **DTG** 000000XXX00                      **HT ID** 1470162976805

<b>Acft</b> F018C	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> MARFORPAC
<b>Custodian</b> VMFA 232			<b>Buno</b> 165192
<b>Fatalities</b> 0			

**Location** FALLON NAS SHORE Approximate LAT/LONG listed. Crash occurred near the initial for visual approach to runway 31R.

**Summary** F/A-18C flying an FCF-A crashed approx. 4 miles SE of NAS Fallon, NV. Pilot ejected, minor injuries.

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 5 of 12

---

**Mishap Date** 08/14/2016      **Time** 2106    **Severity** A FM    **Event Cost** \$37,800,000  
**Reference** VT-21                      **DTG** 000000XXX00                      **HT ID** 1471229487476

**Acft** T045C                      **Count** Y    **Destroyed** Y                      **Major Command** CNATRA  
**Custodian** VT-21    **Buno** 163621  
**Fatalities** 0

**Location** KINGSVILLE NAS SHORE NQI 250R at 16DME

**Summary** T-45C: ACUTE PHYSIOLOGICAL EPISODE RESULTS IN ACTIVATION OF THE EJECTION SEQUENCE BY CREW

---

**Mishap Date** 09/07/2016      **Time** 1305    **Severity** A FM    **Event Cost** \$38,800,000  
**Reference** VT-9                      **DTG** 000000XXX00                      **HT ID** 1473276621057

**Acft** T045C                      **Count** Y    **Destroyed** Y                      **Major Command** CNATRA  
**Custodian** VT-9    **Buno** 165606  
**Fatalities** 0

**Location** MERIDIAN NAS SHORE

**Summary** T-45C: A single T-45C impacted the ground at high energy.

---

**Mishap Date** 09/22/2016      **Time** 1400    **Severity** A FM    **Event Cost** \$64,400,000  
**Reference** VMA-542                      **DTG** 000000XXX00                      **HT ID** 1474587955331

**Acft** AV008B                      **Count** Y    **Destroyed** Y                      **Major Command** MARFORCOM  
**Custodian** MARINE CORPS FORCES COMMAND - MARFORCOM    **Buno** 165354  
**Fatalities** 0

**Location** PACIFIC OCEAN (WESTERN - WESTPAC) KADENA AB WATER Tiger Center ALTRV, overlays W-173

**Summary** AV-8B crashed during day ACM training sortie over Pacific Ocean, pilot ejected safely.

---

**Mishap Date** 10/13/2016      **Time** 0030    **Severity** A FM    **Event Cost** \$0  
**Reference** VQ-3 SEA COMP                      **DTG** 000000XXX00                      **HT ID** 1476394075639

**Acft** E006B                      **Count** Y    **Destroyed** N                      **Major Command** COMNAVAIRPAC  
**Custodian** VQ-3 SEA COMP    **Buno** 164408  
**Fatalities** 0

**Location** TINKER AFB

**Summary** Bird ingested in #2 engine with damage to compressor blades noted upon conditional inspection.

---

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 6 of 12

---

**Mishap Date** 10/20/2016      **Time** 1912      **Severity** A FM      **Event Cost** \$57,512,520  
**Reference** HMH-465      **DTG** 000000XXX00      **HT ID** 1477345861529

**Acft** CH053E      **Count** Y      **Destroyed** Y      **Major Command** MARFORPAC  
**Custodian** HMH-465      **Buno** 164781  
**Fatalities** 0

**Location** YUMA SHORE Combat Town R2301W Yuma Range Complex

**Summary** CH-53E impacted a shipping container while conducting RVL at MAWTS-1 during WTI 1-17

---

**Mishap Date** 10/25/2016      **Time** 1815      **Severity** A FM      **Event Cost** \$74,000,000  
**Reference** VMFA-251      **DTG** 000000XXX00      **HT ID** 1477448751427

**Acft** F018C      **Count** Y      **Destroyed** Y      **Major Command** MARFORCOM  
**Custodian** VMFA-251      **Buno** 164238  
**Fatalities** 0

**Location** TWENTYNINE PALMS EAF SHORE

**Summary** Pilot ejected safely from aircraft during landing at the 29 Palms Expeditionary Landing Field.

---

**Mishap Date** 10/27/2016      **Time** 0937      **Severity** A FM      **Event Cost** \$2,000,001  
**Reference** VMFAT-501 WARLORDS      **DTG** 000000XXX00      **HT ID** 1477594349811

**Acft** F035B      **Count** Y      **Destroyed** U      **Major Command** MARFORCOM  
**Custodian** VMFAT-501 WARLORDS      **Buno** 168057  
**Fatalities** 0

**Location** BEAUFORT MCAS SHORE Landing Pattern

**Summary** FIRE WPN BAY R, IPP FAIL, HYD FAIL B in the landing pattern.

---

10/01/2015 to 08/22/2017

Rpt No: AV-201

Class A Mishaps

Page 7 of 12

**Mishap Date** 11/09/2016      **Time** 1142    **Severity** A FM    **Event Cost** \$84,200,000  
**Reference** VMFA-314      **DTG** 000000XXX00      **HT ID** 1478736762470

<b>Acft</b>	F018A+	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORPAC
<b>Custodian</b>	VMFA-314					<b>Buno</b>	163102
<b>Fatalities</b>	0						
<b>Acft</b>	F018A+	<b>Count</b>	N	<b>Destroyed</b>	N	<b>Major Command</b>	MARFORPAC
<b>Custodian</b>	VMFA-314					<b>Buno</b>	163137
<b>Fatalities</b>	0						

**Location** PACIFIC OCEAN (EASTERN - EASTPAC) SAN DIEGO SHORE

**Summary** F/A-18A: Two F/A-18s have a midair during a HABFM sortie

**Mishap Date** 11/21/2016      **Time** 1548    **Severity** A FM    **Event Cost** \$3,300,000  
**Reference** VFA-122      **DTG** 000000XXX00      **HT ID** 1479838421972

<b>Acft</b>	F018F	<b>Count</b>	Y	<b>Destroyed</b>	N	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	VFA-122					<b>Buno</b>	166847
<b>Fatalities</b>	0						

**Location** LEMOORE NAS SHORE Sidewinder Low Level Between Points B and C

**Summary** F/A-18F: Aircraft impacted a tree during low level training. Aircraft recovered safely.

**Mishap Date** 12/07/2016      **Time** 1836    **Severity** A FM    **Event Cost** \$76,500,000  
**Reference** VMFA-115      **DTG** 000000XXX00      **HT ID** 1481118093282

<b>Acft</b>	F018C	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	MARFORCOM
<b>Custodian</b>	VMFA-115					<b>Buno</b>	163755
<b>Fatalities</b>	1						

**Location** PACIFIC OCEAN (WESTERN - WESTPAC) IWAKUNI MCAS WATER

**Summary** F/A-18C+ Ejection at Night Over Water

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 8 of 12

**Mishap Date** 12/12/2016      **Time** 2118    **Severity** A FM    **Event Cost** \$81,789,705  
**Reference** VMM-265                      **DTG** 000000XXX00                      **HT ID** 1483660001837

<b>Acft</b> MV022B	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> MARFORPAC
<b>Custodian</b> VMM-265			<b>Buno</b> 168027
<b>Fatalities</b> 0			

**Location** PHILIPPINE SEA OKINAWA WATER

**Summary** MV-22 ditched during night AAR training flight.

**Mishap Date** 12/15/2016      **Time** 1056    **Severity** A GM    **Event Cost** \$94,324,924  
**Reference** VAQ-132                      **DTG** 000000XXX00                      **HT ID** 1481939687033

<b>Acft</b> EA018G	<b>Count</b> Y	<b>Destroyed</b> U	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> VAQ-132			<b>Buno</b> 166937
<b>Fatalities</b> 0			

**Location** WHIDBEY ISLAND NAS SHORE NASWI: Hangar 8 Flightline

**Summary** EA-18G: COCKPIT OVER-PRESSURIZED ON DECK CAUSING CATASTROPHIC CANOPY RUPTURE AND SEVERE INJURIES.

**Mishap Date** 12/18/2016      **Time** 0600    **Severity** A GM    **Event Cost** \$3,000,000  
**Reference** VP-10                              **DTG** 000000XXX00                      **HT ID** 1482101347834

<b>Acft</b> P008A	<b>Count</b> Y	<b>Destroyed</b> N	<b>Major Command</b> COMNAVAIRLANT
<b>Custodian</b> VP-10			<b>Buno</b> 168763
<b>Fatalities</b> 0			

**Location** KADENA AB SHORE Kadena AB

**Summary** P-8A: Tow bar separation leads to aircraft/tow collision with damage to nose gear and lower fuselage

**Mishap Date** 01/17/2017      **Time** 1405    **Severity** A FM    **Event Cost** \$38,800,000  
**Reference** VT-9                                **DTG** 000000XXX00                      **HT ID** 1484687820471

<b>Acft</b> T045C	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> CNATRA
<b>Custodian</b> VT-9			<b>Buno</b> 165466
<b>Fatalities</b> 0			

**Location** MERIDIAN NAS SHORE Just prior to runway 28 at KNMM.

**Summary** T-45C: Bird strike during takeoff. MA impacted ground just short of runway during RTB.



10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 9 of 12

**Mishap Date** 01/19/2017      **Time** 0900    **Severity** A GM    **Event Cost** \$5,527,200  
**Reference** VAW-124                      **DTG** 000000XXX00                      **HT ID** 1484856801796

<b>Acft</b> E002C	<b>Count</b> Y	<b>Destroyed</b> N	<b>Major Command</b> COMNAVAIRLANT
<b>Custodian</b> VAW-124			<b>Buno</b> 165295
<b>Fatalities</b> 0			
<b>Acft</b> E002C	<b>Count</b> N	<b>Destroyed</b> U	<b>Major Command</b> COMNAVAIRLANT
<b>Custodian</b> VAW-124			<b>Buno</b> 164483
<b>Fatalities</b> 0			
<b>Acft</b> E002C	<b>Count</b> N	<b>Destroyed</b> U	<b>Major Command</b> COMNAVAIRLANT
<b>Custodian</b> VAW-124			<b>Buno</b> 165298
<b>Fatalities</b> 0			

**Location** NORFOLK NS SHORE

**Summary** E-2C: Improper Engine Oil Utilization

**Mishap Date** 04/05/2017      **Time** 1300    **Severity** A FM    **Event Cost** \$0  
**Reference** HMH-361                      **DTG** 000000XXX00                      **HT ID** 1491429191763

<b>Acft</b> CH053E	<b>Count</b> Y	<b>Destroyed</b> U	<b>Major Command</b> MARFORPAC
<b>Custodian</b> MARINE HEAVY HELICOPTER SQUADRON 361	HMH-361	<b>Buno</b> 164358	
<b>Fatalities</b> 0			

**Location**

**Summary** Aircraft experienced a hard landing and rolled.

**Mishap Date** 04/21/2017      **Time** 1837    **Severity** A FM    **Event Cost** \$88,700,000  
**Reference** VFA-137                      **DTG** 000000XXX00                      **HT ID** 1492776201526

<b>Acft</b> F018E	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> VFA-137			<b>Buno</b> 165904
<b>Fatalities</b> 0			

**Location** CELEBES SEA OTHER SHIP

**Summary** F/A-18E: Aircraft crashed while on final approach to CVN. Pilot ejected safely.

**10/01/2015 to 08/22/2017**

Rpt No:AV-201

**Class A Mishaps**

Page 10 of 12

**Mishap Date** 04/27/2017      **Time** 0657    **Severity** A FM    **Event Cost** \$37,700,000  
**Reference** HSM 78                      **DTG** 000000XXX00                      **HT ID** 1493289747542

<b>Acft</b> MH060R	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> HSM 78			<b>Buno</b> 166549
<b>Fatalities</b> 0			

**Location** PACIFIC OCEAN (WESTERN - WESTPAC) WATER Open Ocean approximately 250 nautical miles East of Guam.

**Summary** MH-60R: Upon takeoff, aircraft experienced an uncommanded right yaw followed by cut gun into water

**Mishap Date** 06/25/2017      **Time** 2217    **Severity** A GM    **Event Cost** \$2,000,000  
**Reference** VMFA-112                      **DTG** 000000XXX00                      **HT ID** 1498470628610

<b>Acft</b> F018A+	<b>Count</b> Y	<b>Destroyed</b> U	<b>Major Command</b> 4TH MAW
<b>Custodian</b> VMFA-112			<b>Buno</b> 162428
<b>Fatalities</b> 0			

**Location** MIRAMAR MCAS SHORE On ramp by Hangar 1

**Summary** FA-18A: Two Marines injured after drip pan fuel caught fire under aircraft. Damage to aircraft also.

**Mishap Date** 06/28/2017      **Time** 2140    **Severity** A GM    **Event Cost** \$0  
**Reference** VAQ-142                      **DTG** 000000XXX00                      **HT ID** 1498697362043

<b>Acft</b> EA018G	<b>Count</b> Y	<b>Destroyed</b> U	<b>Major Command</b> COMNAVAIRPAC
<b>Custodian</b> VAQ-142			<b>Buno</b> 168392
<b>Fatalities</b> 0			

**Location**

**Summary** EA18G damaged starboard wing when re-spreading it failed 40 degrees beyond the normal position down.

**Mishap Date** 07/10/2017      **Time** 1715    **Severity** A FM    **Event Cost** \$70,675,000  
**Reference** VMGR 452                      **DTG** 000000XXX00                      **HT ID** 1499743483243

<b>Acft</b> KC130T	<b>Count</b> Y	<b>Destroyed</b> Y	<b>Major Command</b> 4TH MAW
<b>Custodian</b> VMGR 452			<b>Buno</b> 16500
<b>Fatalities</b> 16			

**Location**

**Summary** KC-130T BUNO 16500 total loss with 16 personnel on board

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 11 of 12

---

**Mishap Date** 07/11/2017      **Time** 1622    **Severity** A GM    **Event Cost** \$0  
**Reference** VMM-261                      **DTG** 000000XXX00                      **HT ID** 1499815425735

**Acft** MV022B                      **Count** Y    **Destroyed** U                      **Major Command** MARFORCOM  
**Custodian** VMM 261    **Buno** 168349  
**Fatalities** 0

**Location** NEW RIVER MCAS MCAS NEW RIVER

**Summary** MAINTAINERS STRUCK BY LIGHTNING ON THE FLIGHT LINE WHILE WORKING ON AIRCRAFT.

---

**Mishap Date** 07/16/2017      **Time** 1500    **Severity** A FM    **Event Cost** \$0  
**Reference** VFA-154                      **DTG** 000000XXX00                      **HT ID** 1500190034570

**Acft** F018F                      **Count** Y    **Destroyed** N                      **Major Command** COMNAVAIRPAC  
**Custodian** VFA-154    **Buno** 166883  
**Fatalities** 0

**Location** .

**Summary** Engine borescope plug backed out in flight causing hot air to burn engine bay and aircraft skin

---

**Mishap Date** 08/05/2017      **Time** 1604    **Severity** A FM    **Event Cost** \$83,195,000  
**Reference** VMM-265                      **DTG** 000000XXX00                      **HT ID** 1501925672884

**Acft** MV022B                      **Count** Y    **Destroyed** Y                      **Major Command** MARFORPAC  
**Custodian** VMM-265    **Buno** 168634  
**Fatalities** 3

**Location** Eastern Coast of Australia

**Summary** On approach to LPD, aircraft struck ship and then impacted water on starboard quarter of the ship.

---

**Mishap Date** 08/05/2017      **Time** 1900    **Severity** A FM    **Event Cost** \$0  
**Reference** VFA-22                      **DTG** 000000XXX00                      **HT ID** 1501986383271

**Acft** F018F                      **Count** Y    **Destroyed** N                      **Major Command** COMNAVAIRPAC  
**Custodian** VFA-22    **Buno** 166976  
**Fatalities** 0

**Location**

**Summary** F-18F impacted round down with right horizontal stabilator upon landing. Diverted successfully.

---

10/01/2015 to 08/22/2017

Rpt No:AV-201

Class A Mishaps

Page 12 of 12

---

<b>Mishap Date</b>	08/09/2017	<b>Time</b>	1238	<b>Severity</b>	A FM	<b>Event Cost</b>	\$2,700,000
<b>Reference</b>	VFC-111	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1502308995787

<b>Acft</b>	F005N	<b>Count</b>	Y	<b>Destroyed</b>	Y	<b>Major Command</b>	NAVAL RESERVE
<b>Custodian</b>	VFC-111					<b>Buno</b>	761533
<b>Fatalities</b>	0						

**Location**

**Summary** F-5N aircraft crashed during a training mission.

---

<b>Mishap Date</b>	08/12/2017	<b>Time</b>	1245	<b>Severity</b>	A FM	<b>Event Cost</b>	\$0
<b>Reference</b>	VFA-146	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1502542138704

<b>Acft</b>	F018E	<b>Count</b>	Y	<b>Destroyed</b>	U	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	VFA-146					<b>Buno</b>	165865
<b>Fatalities</b>	0						

**Location**

**Summary** Aircrew ejected after landing following aircraft divert from USS ship due to engine anomalies.

---

<b>Mishap Date</b>	08/17/2017	<b>Time</b>	0630	<b>Severity</b>	A GM	<b>Event Cost</b>	\$0
<b>Reference</b>	VAQ 135	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1502993969787

<b>Acft</b>	EA018G	<b>Count</b>	Y	<b>Destroyed</b>	N	<b>Major Command</b>	COMNAVAIRPAC
<b>Custodian</b>	VAQ 135					<b>Buno</b>	166946
<b>Fatalities</b>	0						

**Location** NS Rota

**Summary** NAVY EA-18G FOD DAMAGE TO RIGHT ENGINE DURING ENGINE STARTUP PROCESS AT NAVAL STATION ROTA, SPAIN

---

<b>Mishap Date</b>	08/17/2017	<b>Time</b>	2247	<b>Severity</b>	A FRM	<b>Event Cost</b>	\$0
<b>Reference</b>	HSM-73	<b>DTG</b>	000000XXX00	<b>HT ID</b>			1503129608290

<b>Acft</b>	MH060R	<b>Count</b>	Y	<b>Destroyed</b>	N	<b>Major Command</b>	
<b>Custodian</b>	CNAP STAFF					<b>Buno</b>	168124
<b>Fatalities</b>	0						

**Location**

**Summary** Aircraft SONAR Transducer lost at sea.

---

**10/01/2015 to 08/22/2017**

Rpt No:AV-201

**Class A Mishaps**

Page 13 of 12

---