



#561: Not What We Meant By "Recycling"

For the record, that's a spot cooler in a data center that someone has elevated on an obsolete (and abandoned) network switch (so the condensate would drain).

There were footprints on the control panel of the spot cooler, as well, showing that it had been repurposed as a ladder.

Just another example of two wrongs not making a right.

<< [Previous](#) | [Next](#) >>

Visit the Photo of the Week archives at
http://www.public.navy.mil/navsafecen/Pages/photo/photo_archives.aspx