



#554: Actual Instruction #1—Locate Box Cutter

Our contributor found this on a fork truck during a safety inspection. The original clasp had broken. Not to worry: Any nearby fire will eventually melt the zip tie. And it could have been worse, our contributor noted—the guy who “fixed” it could have used duct tape.

<< [Previous](#) | [Next](#) >>

Visit the [Photo of the Week archives](#)